
FCE Project #	16	27	Date Performed:	5/26/20			
Client:	281 Middlesex LLC						
Location:	4 Holly Lane, Darien						
Observed by:			Wayne D'Avan	e D'Avanzo			
Test Hole 1:							
	0-14"	Topsoil					
	14-22"	Brown Sil	ty Loam				
	22-50"	Grey Gravel and Silt					
	No Ground	l Water		1/2			
	Mottling @	22"					
	No Ledge						
Test Hole 2:							
	0-13"	Topsoil					
	13-22"	Brown Sil	ty Loam				
	22-49"	Grey Grav	vel and Silt				
	No Ground Water						
	Mottling @	22"					
	No Ledge						


Conducted b	y:	0	thers	Project:	1627
Location:		4 Holly Lane		Town:	Darien
Client :	281	Middlesex R	oad	Date:	5/26/20
Weather con	ditions prior to a	nd during test	s:		
Clear					
Single Lot:		X	Subdivision:		
Diameter of Hole:		8"	Depth of Hole	e: 30"	
PT-1					Design
Pre-Soak @	: 1:00 PM				1"/30 Min.
	Time	Depth to	Drop in	Soil Percolation Rat	
Time	Increment	Water	inches	Time to drop 1 inch	
1:40 AM		4"	_		
1:50 AM	10 Min.	9"	5"	2.0 Min.	
2:00 AM	10 Min.	11 1/2"	2 1/2"	4.0 Min.	
2:10 AM	10 Min.	12 1/2"	1"	10.0 Min.	
2:20 AM	10 Min.	13 1/4"	3/4"	13.3 Min.	
2:30 AM	10 Min.	13 3/4"	1/2"	20.0 Min.	
	W 100 - 40 1 00	100-0427			


2:40 AM 10 Min. 14 1/8"




3/8"


26.7 Min.








NOT TO SCALE











COARSE PARTICLE SEPARATOR

